

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #1 : Kindergarten
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 150
Last Re-Assessment:

Area (sqft): 710

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Foil Face	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #2 : Kindergarten #2
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 146
Last Re-Assessment:

Area (sqft): 710

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	S0088	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	S0089	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #3 : Coatroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 144
Last Re-Assessment:

Area (sqft): 240

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0088	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0089	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #4 : Kindergarten #1
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 142
Last Re-Assessment:

Area (sqft): 710

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0088	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			A	Y		100			%	V0089	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #5 : Washroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 146A
Last Re-Assessment:

Area (sqft): 25

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall Compound			C	Y		100			%	V0095	None Detected	N.D.	None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0094	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #6 : Washroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 142A
Last Re-Assessment:

Area (sqft): 25

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall Compound			C	Y		100			%	V0095	None Detected	N.D.	None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0094	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #7 : Storage
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 148
Last Re-Assessment:

Area (sqft): 115

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0088	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	N		100			%	V0089	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #8 : Janitor
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 140
Last Re-Assessment:

Area (sqft): 230

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Aluminum			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0088	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	N		100			%	V0089	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #9 : Staff room
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 138
Last Re-Assessment:

Area (sqft): 745

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood		Drywall (no compound)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)		Ceiling Tiles (lay-in)	C	N		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0088	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	N		100			%	V0089	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0072	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	S0093	Chrysotile	10-25%	Confirmed Asbestos	NF
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #10 : Washroom
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 134
Last Re-Assessment:

Area (sqft): 65

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in)		Ceiling Tiles (lay-in)	C	N		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened)			C	Y		100			%	V0089	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #11 : Office
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 132
Last Re-Assessment:

Area (sqft): 140

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened)			C	N		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #12 : Printer
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 116
Last Re-Assessment:

Area (sqft): 85

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened)			C	N		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #13 : Vestibule
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 114
Last Re-Assessment:

Area (sqft): 55

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall Compound			C	Y		100			%	V0095	None Detected	N.D.	None	
Ceiling		Drywall Compound			C	Y		100			%	V0095	None Detected	N.D.	None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0094	None Detected	N.D.	None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0094	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #14 : Kitchen
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 112A
Last Re-Assessment:

Area (sqft): 355

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened)			C	Y		100			%	V0075	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	S0076	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	S0096	None Detected	N.D.	None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #15 : Daycare cafeteria
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 112
Last Re-Assessment:

Area (sqft): 690

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened)			C	N		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #16 : Hallway
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #:
Last Re-Assessment:

Area (sqft): 525

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tile (mechanically fastened)			C	N		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0072	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #17 : Daycare cafeteria
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 110
Last Re-Assessment:

Area (sqft): 790

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			A	Y		100			%	V0071	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened)			A	Y		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	
Wall		Roughcast		Plaster	A	Y		100			%	V0074	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #18 : General office
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 129
Last Re-Assessment:

Area (sqft): 270

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened)			C	Y		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0072	None Detected	N.D.	None	
Wall		Drywall Compound			A	Y		100			%	C0097	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	C0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #19 : Boys washroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 133
Last Re-Assessment:

Area (sqft): 125

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)		Ceiling Tiles (lay-in)	C	Y		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0097	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Roughcast		Plaster	A	Y		100			%	V0074	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #20 : Girls washroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 135
Last Re-Assessment:

Area (sqft): 125

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)		Ceiling Tiles (lay-in)	C	Y		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0097	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0089	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Roughcast		Plaster	A	Y		100			%	V0074	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #21 : Resource
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 131
Last Re-Assessment:

Area (sqft): 615

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	
Wall		Roughcast		Plaster	A	Y		100			%	V0074	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #22 : Office
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 137
Last Re-Assessment:

Area (sqft): 250

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	N		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0088	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0097	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	
Wall		Roughcast		Plaster	A	Y		100			%	V0074	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #23 : Office
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 139
Last Re-Assessment:

Area (sqft): 250

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	N		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0088	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0097	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #24 : Storage
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 141A
Last Re-Assessment:

Area (sqft): 95

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	N		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	S0098	None Detected	1-5%	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	
Wall		Roughcast		Plaster	A	Y		100			%	V0074	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #25 : Boiler room
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 141B
Last Re-Assessment:

Area (sqft): 215

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)			C	N		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Concrete (poured)			B	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic			B	Y		100			%	V0098	None Detected	1-5%	None	
Piping	Domestic Water (hot And Cold)	Fibreglass	Straight		B	Y		100			%	V0000	Non-Asbestos		None	
Piping	Domestic Water (hot And Cold)	Fibreglass	Fitting		B	Y		100			%	V0000	Non-Asbestos		None	
Piping	Hot Water Heating	Fibreglass	Straight		B	Y		100			%	V0000	Non-Asbestos		None	
Piping	Hot Water Heating	Fibreglass	Fitting		B	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			B	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			B	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			B	Y		100			%	V0086	None Detected	N.D.	None	
Wall		Roughcast		Plaster	B	Y		100			%	V0074	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #26 : Mechanical room
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 141
Last Re-Assessment:

Area (sqft): 370

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Roughcast			C	Y		100			%	S0083	Not Analyzed	0.1-1%	Confirmed Asbestos	PF
Duct	Supply Air	Parging Cement	ALL	Canvas	B	Y		100			%	S0100	Chrysotile	25-50%	Confirmed Asbestos	F
Floor		Concrete (poured)			B	Y		100			%	V0000	Non-Asbestos		None	
Piping	Domestic Water (hot And Cold)	Fibreglass	ALL	Canvas	B	Y		100			%	V0000	Non-Asbestos		None	
Piping	Hot Water Heating	Fibreglass	ALL	Canvas	B	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (poured)			B	Y		100			%	V0000	Non-Asbestos		None	
Wall		Roughcast			A	Y		100			%	S0099	Not Analyzed	1-5%	Confirmed Asbestos	PF

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #27 : Storage
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 143A
Last Re-Assessment:

Area (sqft): 205

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic			B	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			B	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			B	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			B	Y		100			%	V0086	None Detected	N.D.	None	
Wall		Roughcast		Plaster	B	Y		100			%	V0074	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #28 : Gymnasium
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 143
Last Re-Assessment:

Area (sqft): 2240

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Adhesive/mastic		Ceiling tiles (glue-on)	C	N		100			%	S0092	None Detected	N.D.	None	
Ceiling		Ceiling tiles (glue-on)			C	Y		100			%	S0091	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0081	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #29 : Office
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 143B
Last Re-Assessment:

Area (sqft): 120

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)		Ceiling Tiles (lay-in)	C	N		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0097	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	S0081	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #30 : Gym storage
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 143C
Last Re-Assessment:

Area (sqft): 240

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Wood			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall (no compound)		Ceiling Tiles (lay-in)	C	N		100			%	V0090	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0097	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0081	None Detected	N.D.	None	
Piping	Domestic Hot Water	Fibreglass	Straight	Canvas	C	N		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #31 : Kindergarden WC
Survey Date: 2017-03-20

Site: Écoles
Floor: RDC

Building Name: 155 : École Pinewood A
Room #: 150A
Last Re-Assessment:

Area (sqft): 15

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall Compound			C	Y		100			%	V0095	None Detected	N.D.	None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0094	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #32 : Hallway
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 100A
Last Re-Assessment:

Area (sqft): 1220

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall Compound			C	Y		100			%	S0095	None Detected	N.D.	None	
Ceiling		Drywall (no compound)			C	Y		100			%	S0094	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0070	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #33 : Principal
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 127
Last Re-Assessment:

Area (sqft): 185

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened)			C	Y		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0072	None Detected	N.D.	None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #34 : Storage
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 127
Last Re-Assessment:

Area (sqft): 120

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Roughcast		Plaster	C	Y		100			%	V0101	None Detected	N.D.	None	
Floor		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Plaster			A	Y		100			%	V0074	None Detected	N.D.	None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	
Wall		Roughcast		Plaster	A	Y		100			%	V0074	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #35 : Computer lab
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 123
Last Re-Assessment:

Area (sqft): 350

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tile (mechanically fastened)			A	Y		100			%	V0075	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	
Wall		Roughcast		Plaster	A	Y		100			%	S0074	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #36 : Daycare office
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 121
Last Re-Assessment:

Area (sqft): 200

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tile (mechanically fastened)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0071	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened)			C	Y		100			%	S0075	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall Compound			A	Y		100			%	V0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	V0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #37 : Hallway
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 100
Last Re-Assessment:

Area (sqft): 2545

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel			C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			A	Y		100			%	V0071	None Detected	N.D.	None	
Ceiling		Roughcast		Plaster	C	N		80			%	S0101	None Detected	N.D.	None	
Ceiling		Ceiling Tile (mechanically fastened)			C	Y		100			%	V0075	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0070	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0072	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #38 : Office
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 119
Last Re-Assessment:

Area (sqft): 150

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Carpet			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #39 : Office
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 117
Last Re-Assessment:

Area (sqft): 150

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	S0082	None Detected	N.D.	None	
Floor		Carpet			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #40 : Library
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 108
Last Re-Assessment:

Area (sqft): 805

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	S0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0072	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall Compound			A	Y		100			%	S0087	None Detected	N.D.	None	
Wall		Drywall (no compound)			A	Y		100			%	S0086	None Detected	N.D.	None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #41 : Stairs
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 124
Last Re-Assessment:

Area (sqft): 40

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall Compound			C	Y		100			%	V0095	None Detected	N.D.	None	
Ceiling		Drywall (no compound)			C	Y		100			%	V0094	None Detected	N.D.	None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #42 : Stairs
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: ESC-2
Last Re-Assessment:

Area (sqft): 125

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #43 : Boys washroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 109
Last Re-Assessment:

Area (sqft): 120

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #44 : Girls washroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 111
Last Re-Assessment:

Area (sqft): 120

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #45 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 107
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #46 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 105
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #47 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 103
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #48 : Stairs
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: ESC-1
Last Re-Assessment:

Area (sqft): 120

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #49 : Vestibule
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 101
Last Re-Assessment:

Area (sqft): 75

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #50 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 102
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #51 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 104
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #52 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 106
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #53 : Vestibule
Survey Date: 2017-03-20

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 118
Last Re-Assessment:

Area (sqft): 95

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #54 : Janitor
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 119
Last Re-Assessment:

Area (sqft): 50

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #55 : Sprinkler storage
Survey Date: 2015-10-22

Site: Écoles
Floor: Rez-de-chaussée

Building Name: 155 : École Pinewood A
Room #: 115
Last Re-Assessment:

Area (sqft): 90

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0072	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #56 : Stairs
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: ESC-2
Last Re-Assessment:

Area (sqft): 225

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #57 : Washroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 212
Last Re-Assessment:

Area (sqft): 120

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #58 : Washroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 210
Last Re-Assessment:

Area (sqft): 120

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #60 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 206
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #61 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 204
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #62 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 202
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #63 : Hallway
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 200
Last Re-Assessment:

Area (sqft): 1080

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	S0071	None Detected	N.D.	None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	S0070	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #64 : Stairs
Survey Date: 2015-10-22

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: ESC-1
Last Re-Assessment:

Area (sqft): 235

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Drywall and joint compound			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #65 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 201
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #66 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 203
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

ALL DATA REPORT

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #67 : Classroom
Survey Date: 2017-03-20

Site: Écoles
Floor: Étage

Building Name: 155 : École Pinewood A
Room #: 205
Last Re-Assessment:

Area (sqft): 740

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Steel		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Aluminum		Ceiling Tiles (lay-in)	C	N		100			%	V0000	Non-Asbestos		None	
Ceiling		Ceiling Tiles (lay-in)			C	Y		100			%	V0082	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic			A	Y		100			%	V0069	None Detected	N.D.	None	
Wall		Concrete (precast)			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Drywall and joint compound			A	Y		100			%	V0000	Non-Asbestos		None	

Client: Commission scolaire Sir Wilfrid-Laurier
Location: #68 : Extérieur du bâtiment
Survey Date: 2017-03-20

Site: Écoles
Floor: NA

Building Name: 155 : École Pinewood A
Room #: NA
Last Re-Assessment:

Area (sqft): 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (splined)			C	Y		100			%	S0104	Chrysotile	25-50%	Confirmed Asbestos	PF
Other	Window	Caulking			A	Y		100			%	V0102	Chrysotile	0.1-1%	Confirmed Asbestos	NF
Wall		Roughcast			A	Y		100			%	S0103	None Detected	N.D.	None	

Photo pour S102

Legend:

Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
V####	Material visually similar to numbered sample collected	LF	Linear feet	V	Visible
V0000	Known non-asbestos material	EA	Each	AP	Air Plenum
V9000	Visually identified as an asbestos material	%	Percentage	F	Friable material
V9500	Material is presumed to be an asbestos material			NF	Non Friable material
				PF	Potentially Friable material

Access		Condition	
A	Accessible to all building occupants	Good	No visible damage or deterioration
B	Accessible to maintenance and operations staff without a ladder	Fair	Minor, repairable damage, cracking, delamination or deterioration
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas	Poor	Irreparable damage or deterioration with exposed and missing material
D	Not normally accessible		

Visible		Air Plenum	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).	Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.		

Colour Coding	
	The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code).
	The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling.